WITNESSES

46.

CITY & STATE	TELEPHONE
Wm Patrick	Loakso
	Um Patrick

atality/Catastrophe Report u Aug 8, 2002 9:16am

eporting ID	1050210	Previous A	Previous Activity (Type & Number) 0					Event Numbe	Γ	10168107	′0
stablishment	Establishment Name	Osborne C	onstruction Con	pany				Employer ID			1000
morniation	Site Address	100th & C Fort Wain	100th & Chestnut Fort Wainwright AK 99703				City Code	0801	County Code	090	
		Site Phone	(907) 356-1160	Site FAX	(907) 356-2	949					
	Mailing Address	100th & C Fort Wain	hestnut wright, AK 9970)3							
	Event Address	,						Primary	1542	No. of	200
ndustry &)wnership	Type of Business							SIC		Employees	
	Ownership	A. Private	Sector			Date	08/05	5/02	Time		
Receipt	Reported By					Date		,, 02	<u> </u>	<u> </u>	
nformation	Job Title					Telepl	none	<u></u>			
Employee Representation	Group Name(s):										
Classification	B. Catastroph				ber of Fatalities	Num	ber of	Nun	nber of	Number	Unaccounte
Event Description	Event Date	Е	vent Time	Num	per of ratantics	Hosp	italized uries	NonHo	spitalized juries		for 0
*	08/05/02		08:45 am		0		1		0	<u> </u>	
	11										
	Type of Even	Fall from	Height	s waiting	g for his part	ner to	finish r	igging	a wall s	ection to	be picked
	An employee and put into p had the victin When finished because they the other end	on the wall lace. The ern help snapping lace in the of the build loose suddentim suffered	framing crew wa mployee asked the lines on the 2nd fi ines the acting le way of where the ing pulling up cli and the viction and a broken back,	loor decad had the walls was He b	k. All employee yould stand. I bent down to	yees w pull up the vic pull up to a flo tracture	ere we the Metim under the close or ope ed skull	aring fa filler cli attached ip with ning, la l.	ill protections (one in the interest of the in	ction and use anchors, when anchors, anchors, and	hooked u ors) walked to nulled ur
Preliminary Description Action	An employee and put into p had the victin When finished because they the other end	on the wall lace. The ern help snapping lace in the of the build loose suddentim suffered	framing crew wa nployee asked the lines on the 2nd the ines the acting le way of where the ing pulling up cling	loor decad had the walls was He b	k. All employee yould stand. I bent down to	yees w pull up the vic pull up to a flo tracture	ere we of the Metim under the closer opered skull O(s) A	aring fa filler cli attached ip with ning, la l. ssigned	ill protections (one in the interest of the in	ction and use anchors, when anchors, anchors, and	hooked u ors) walked to nulled ur
Description	An employee and put into p had the victin When finished because they the other end the clip came below. The vicinity of the vi	on the wall blace. The er help snap d snapping l were in the of the build loose sudde ictim suffere	framing crew wa mployee asked the lines on the 2nd fi ines the acting le way of where the ing pulling up cli and the viction and a broken back,	loor decad had the walls was He b	k. All employee yould stand. I bent down to	yees w pull up the vic pull up to a flo tracture	ere we the Metim under the close or ope ed skull	aring fa filler cli attached ip with ning, la l. ssigned	ill protections (one in the interest of the in	ction and use anchors, when anchors, anchors, and	hooked u ors) walked to nulled ur
Description .	An employee and put into phad the victing When finished because they the other end the clip came below. The vicinity Inspection Planned?	on the wall blace. The er help snap d snapping l were in the of the build loose sudde ictim suffere	framing crew wa mployee asked the lines on the 2nd to ines the acting le way of where the ing pulling up cli- and and the viction and a broken back, or(s) Assigned	loor decad had the walls was He b	k. All employee yould stand. I bent down to	yees w pull up the vic pull up to a flo tracture	ere we of the Matim under the closer opered skull O(s) A	aring fa filler cli attached ip with ning, la l. ssigned	ill protections (one in the interest of the in	ction and use anchors, when anchors, anchors, and	hooked u ors) walked to nulled ur
Description Action Strategic	An employee and put into phad the victim When finished because they the other end the clip came below. The vicinity Inspection Planned? Yes CONSTRUCT	on the wall blace. The er help snap d snapping l were in the of the build loose sudde ictim suffere Superviso S TION	framing crew wa mployee asked the lines on the 2nd the ines the acting le way of where the ing pulling up cli enly and the viction and a broken back, or(s) Assigned	loor decad had the walls was He b	k. All employee yould stand. I bent down to	yees w pull up the vic pull up to a flo tracture	ere we of the Matim under the closer opered skull O(s) A	aring fa filler cli attached ip with ning, la l. ssigned	ill protections (one in the interest of the in	ction and use anchors, when anchors, anchors, and	hooked u ors) walked to nulled ur
Description Action Strategic Initiatives National	An employee and put into phad the victim When finished because they the other end the clip came below. The vicinity Inspection Planned? Yes CONSTRUCT	on the wall blace. The er help snap d snapping l were in the of the build loose sudde fictim suffere Supervisor STION	framing crew wa mployee asked the lines on the 2nd the ines the acting le way of where the ing pulling up cli enly and the viction and a broken back, or(s) Assigned	loor decad had the walls walls went to collapse	k. All employee yould stand. I bent down to	yees w pull up the vic pull up to a flo tracture	ere we of the Matim under the closer opered skull O(s) A	aring fa filler cli attached ip with ning, la l. ssigned	ill protections (one in the interest of the in	ction and use anchors, when anchors, anchors, and	hooked u ors) walked to nulled ur

Investigation Summary

Thu Aug 8, 2002 9:42am

Thu Aug 6, 2002	7.42aiii		OSHA-36 Establishment Name
Reporting ID	Investigation	OSHA-36	OSHA-30 Establishment reame
Ropording 12	Summary Number	Number	
	201681012	101681070	Osborne Construction Company
1050210	201001012		
Event Date	08/05/02	Event Time	08:45 am
Type of Event	Fall from Height		

Inspection Number/ Establishment Name	303702237 Osborne Construction Company
	Joel Wallender
Sex:	M. Male
Age:	34
Injury:	B. Hospitalized
Nature:	12 Fracture
Part of Body:	03 Back
Source of Injury:	42 Working surface
Event Type:	05 Fall (from elevation)
Environmental Factor:	13 Working surface or facility layout condition
Human Factor:	01 Misjudgment of hazardous situation
Task:	B Not Regularly Assigned
Substance Code:	
Occupational Code	567 - CARPENTERS

Abstract:

An employee fell through a stairwell opening 18'6" to the concrete floor in the basement. The victim was pulling up anchor clips for attachment points for fall protection from the building perimeter. The clips were attached wher the walls would be located. The victim was not attached to an anchor while pulling another from the floor. As the victim pulled up on the clip the nails pulled loose and the employee went backwards and down the stairwell shaft. The victim sustained a broken back, collapsed lung, and the back of his head fractured.

CONSTRUCTION ACCIDENT INFORMATION

Project Level Information

Type of Construction		
A New project or new addition		
End-use Type of Construction Site		
B Multi-family dwelling		
If a building site, number of stories (in feet):	2	
If a non-building structure, height (in feet):	0	
Project Cost		
•		
F \$5,000,000 to \$20,000,000		

Victim Level Information

Victim Ecter into me	
Victim's Name	Joel Wallender
Cause of Fatality / Accident	Fall through opening (other than roof)
Distance of the Fall (in feet)	18
Height above ground (or floor) of the worker when the fall occurred (ft)	6
Operation being performed by the victim	Other Activities-Post Decking Detail Work
Contributing Operation (if different from the operation above)	

Inspection Report

Fri Sen 13, 2002 1:49pm

Rpt ID	Assignment Nr.	CSHO ID	Duput	moperation	Opt. Insp. Nr.
1050210	0	L4990	S8701	303702237	260-02

	1.7		Osborne Con	struction	Company		
Establishme Site	100th Street & C	Chestnut	TOSSES SERVICES	Site Phone	(907) 356-1160	FAX	(907) 356-2949
Address Mailing Address	100th Street & C	Chestnut		Mail Phone	(907) 356-1160	Mail FAX	(907) 356-2949
Controlling	Osborne Constr			Employ	ver ID		
Corp Ownership	A. Private Secto	r		City	0801	County	090
Legal Entity		A. Corporation	Previous Activ	ty (State C	Only)		

			Related Activity			
Туре	Number	Satisfied	Туре	Number	Satisfied	
A. Accident	101681070					

E i Fachlishmont	73	Advance Notice?	No	Category	S. Safety
Employed in Establishment		Union?	No	Primary SIC	1522
Covered By Inspection		Walkaround?	No	Secondary SIC	
Controlled By Employer	302	Interviewed?	Yes	Inspected	
		interviewed:			

TIMPOULE - JF -	A. Fatality/Catastrophe	Reason No Inspection
Scope of Inspection	A. Comprehensive Inspect	ion
Classification	Safety Planning Guide/Con	nstruction
Strategic Initiatives	CONSTRUCTION	
National Emphasis		
Local Emphasis	AKS	

Anticipatory Warrant Served?	No	Denial Date	Date ReEntered	Date ReDenied	ReEntered	
Anticipatory Subpoena Served?	No					

	100/07/03	10:55	First Closing Conference	09/10/02	14:59
Entry	08/05/02				
Opening Conference	08/05/02	11:06	Second Closing Conference		16.00
Walkaround	08/05/02	11:06	Exit	09/10/02	16:02
Days On Site	5		Case Closed		
			No Citations Issued		

Type	ID	Optional Information

		0	Date	
CSHO Signature	11/2	Patrick Lasker		16 Sept 82
	um.	I walk Caused		18 200

)SHA-200 Data/Safety and Health Program Evaluation

i Sep 13, 2002 10:07am

stablishment اame	Osborne Construction Company			Ownership	A. Private Sector
ite Address	100th Street & Chestnut Fort Wainwright, AK 99703	Site Phone	(907) 356-1160	Site FAX	(907) 356-2949
lailing ddress	100th Street & Chestnut Fort Wainwright, AK 99703	Mailing Phone	(907) 356-1160	Mailing FAX	(907) 356-2949
Controlling Corp	Osborne Construction Company			Employer ID	

			[A-200]	DATA	4			1	ata No vailab		· · · · · · · · · · · · · · · · · · ·			ial Log Year	N	A	# Of Veeks	0
AT:	E 19	41 1	LWDII RATE Cases	19.0	Y	og ear Occupa	1999 itional) } .	ployme verage ases		342	2	1	l Hours orked		15	7755	
(1) x. of tality ates	Cases	(3) Cases With Days Away	Days Away	Workdays	(6) Cases w/o Lost Workdays	Diseases/	Diseases	Toxic Agents		(7e) Disorders Physical Agents	(7f) Repeat Trauma	(7g) Other	(8) Nor. of Fatality Dates	i .	(10) Cases With Days Away			(13) Cases w/o Lost Workdays
0	15	5	78	152	3	0	0	0	0	0	0	0	0	0	0	0	0	0

******		OSH	A-200	DATA				1	ata No vailabl					ial Log Year	N	A 1	# Of Veeks	0
AT	E 13	.9	LWDII RATE Cases	15.9	Y	og ear	2000) l .	ployme verage		358	3	1	l Hours orked		15	1137	
of ality stes	(2) Lost	(3) Cases	(4)	Workdays	(6) Cases w/o	(7a) Skin Diseases/	(7b) Dust Diseases	(7c) Respiratory Toxic Agents	(7d) Poisons	(7e) Disorders Physical Agents	(7f) Repeat Trauma	(7g) Other	(8) Nbr. of Fatality Dates	,	(10) Cases With Days Away			(13) Cases w/o Lost Workdays
)	12	5	59	47	4	0	0	0	0	0	0	0	0	0	0	0	0	0

		Y OSH	IA-200	DATA					ata No vailab	1				ial Log Year	N	n :	# Of Veeks	0
VI AT	E 12	•	LWDII RATE	12.5	Y	og ear Occupa	2001	A	ployme	1	689)	1	d Hours orked			7509	
of lity es	(2) Lost Workday Cases	(3) Cases With Day Away	(4) Nbr. of sDays Away	Workdays	(6) Cases w/o	(7a) Skin Diseases/	(7b) Dust Diseases	(7c) Respiratory Toxic Agents	(7d) Poisons	(7e) Disorders Physical Agents	(7f) Repeat Trauma	(7g) Other	(8) Nbr. of Fatality Dates		(10) Cases With Days Away	(11) Nbr. of Days Away		(13) Cases w/o Lost Workdays
	26	22	254	234	10	0	0	0	0	0	0	0	0	0	0	0	0	0

Inspection Narrative

Fri Sep 13, 2002 1:49nm

			Inspection Nr.	303702237
			Opt. Case Number	260-02
Establishment N	lame Osborn	e Construction Compar	ny	
Legal Entity	A. Corporation	Type of Business	Construction	·- ·

Additional Citation Mailing Addresses

Osborne Construction Company

ATTN: Paul Herbold (425) 827-4221

PO Box 97010

Kirkland, WA 98083-9710

Organized Employee Groups

Authorized Employee Representatives

Name Mike Ritchie	Title	Function	Walk Around?
an Revermann	Project Engr, Osborne	10	N
eff Crawford	Field Project Engr,	I	N
	Superintendent, Osborne	IC	Ÿ
Chris Seeley	Osborne	ΙO	v
im Frink	Quality Control, Osborne	ÕĨ	v
Aatt Emerson	Framing Foreman, Osborne	ίο	N

Entry	08/05/02	10.55			
<u> </u>		10:55	First Closing Conference	09/10/02	14:59
Opening Conference	08/05/02	11:06	Second Closing Conference		
Walkaround	08/05/02	11:06	Exit	09/10/02	16.02
			Case Closed	02/10/02	16:02

	Penalty Reduc	ction Factors		
Size 0	Good Faith	25	History	10
F.11				

7. 1.			
Followup Inspection?	1		
LUMUWUD HISDACHAN /	1 1/2	Reason	
and an appection.	: ¥	I K eacon	I otom whom - C
-		11000011	Later phase of construction

Coverage Information/Additional Comments

SAFETY NARRATIVE

Osborne Construction Company 3701 Braddock Street Fairbanks, Alaska 99701

On 5 August 2002 at 1106 am I began an opening conference with the Superintendent of On 5 August 2002 at 1106 am 1 began an opening conference with the Superintendent of Osborne Construction Company at a housing project on Fort Wainwright, Alaska. This inspection was assigned to me by my supervisor. This inspection is due to an accident, where an employee fell through a stairwell opening, 18'6" to a concrete floor in the basement. The employee fell through a stairwell opening, 18'6" to a concrete floor in the basement. The employee fell through a stairwell opening, 18'6" to a concrete floor in the basement. The has a collapsed lung. The accident happened at approximately 0800 but the victim was not found till 0839 am. The victim is still in the Providence Hospital in Anchorage. Alaska. and found till 0839 am. The victim is still in the Providence Hospital in Anchorage, Alaska, and does not remember anything involved in the accident, except what others have told him. This employee had been on the job for 1.5 weeks, he was a carpenter with the framing crew setting exterior walls and then setting the interior walls. All the wall sections were manufactured in Anchorage, trucked to Fairbanks and the Fort Wainwright job site, then raised by crane on the site and railed in place.

All the employees that work above 6' have been trained in fall protection prior to starting work. The crew working on the 2nd floor deck were wearing fall protection and tied off. The wisting was tied off at the contract the contract that the contract that the contract the contract that the contract the contract that the contract that the contract the contract that the contract that the contract the contract that the contract th off. The victim was tied off at one time, then the leadman lost track of him. When the victim was found, he was still wearing his harness and lanyard. The medics that responded cut the

body narness from the victims body.

The units in which the framing crew was working was a 2 story building with a 7' high storage section for a basement. The building has 4 units, these units are: unit A - B - B reverse - A reverse; with A's being 4 bedroom and B's being 5 bedroom units. The framing crew was working in the confines of unit A on the 2nd floor. Units B and B reverse have the was working in the confines of unit A on the 2nd floor. Units B and A reverse (the end stairwells to the front of the building along the outside wall. Units A and A reverse (the end units) have stairwells located more towards the center of the units floor plane

units) have stairwells located more towards the center of the units floor plans.

The victim was assigned by an acting leadman to remove 2 Miller anchorage clips from the floor, because they were installed where the exterior walls would be set. The victim ws harnessed and attached to a retractable while working in unit B. The leadman got busy and lost track of the victim. Work started on the deck about 0705 am and at about 0730-0800 am they started asking about the victim and where he got off to. The victim was found at

As the floor joist and decking crews begin the decking the vare harnessed and tied off at the nearest place to attach to as the begin the decking from the outside wall working toward the opposite side. Consequently, the clips are placed in the exact position of the

toward the opposite side. Consequently, the clips are placed in the exact position of the exterior wall placement, when the decking crew lays their first course of plywood.

The victim was waiting on his working partner to finish rigging exterior walls they would be setting, and in the meantime he wanted something to do so he asked the leadman and he stated that he could remove the anchor clips for the wall panels. The leadman stated that he told the victim to remove the clips within the area (or unit A) and not through to the other end of the building which would be units B, B reverse and A reverse the end unit, but he did not appear to be specific.

he did not appear to be specific.

The victim proceded down the length of the building removing clips, the leadman and his partner went back to work, laying out and snapping lines for the interior walls. The clip was located towards the front of building (S) about 3' from the edge. The clip is also (E) located towards a front inside corner and about 1' from the edge. The stairwell opening is about 7' towards a front of the building. S & N sides of stairwell opening are 6'6", E & W are 9'6" from the (S) front of building. The victim apparently stood on the deck between the outside edge and the inside stairwell opening. As he was bent over to drive the hammers claws into and under the clip and then pull up the nails or pull the clip up, it appears that he lunged backwards and fell through the opening after the clip or nails gave way. The clip was bent towards the opening suggesting that the force was heading towards him and the stairwell behind. I don't think anyone will know for sure what actually happened, unless the victims memory of the events come back.

Employees on the 2nd floor deck asked about the victim and where he had gone, no one

Employees on the 2nd floor deck asked about the victim and where he had gone, no one new and assumed he was in the restroom, when they saw a tool belt that looked like his. But the tool belt belonged to the leadmans helper. When they finished the leadmans partner began the tool belt belonged to the leadmans helper. sweeping the deck. When he got to the A reverse unit stairwell he hollered heads up and then looked through the opening to make sure no one was below when he sweeped the deck clean. He noticed someone on the ground. It appeared that an employee was lying on his back working because he noticed the victims arms moving around. As he looked harder he noticed the blood because he noticed the victims arms moving around. and then realized it was the victim. He hollered for help, a man was down, the leadman got on his radio and raised the alarm for help and an ambulance. Apparently the victim landed on

a box or 2 boxes of nails. Many of the employees that worked with the victim stated that the victim and his orking partner were the safest employees on the deck and they were always telling the other mployess to get attached, or tell them them the proper safe way to do something.

The employers corporate safety officer and the superintendent feel that they are a safe ompany, and that maybe in this case the employee caused the accident. Therefore, an employee __isconduct defense may be in the works. After looking into this alleged defense I found the

Employer has established work rules and policies designed to prevent the violation. following conclusions:

The employer has an established written safety program; it has a fall protection plan, and it covers training on walking/working surfaces, and fall protection training before

It has adequately communicated those rules and policies to its employees. the employee starts work. Fall protection training has been given and is documented for employees and for the victim that took the fall. Safety meetings have covered fall protection and safety meetings are held on Mondays with documentation, and daily tool box meetings take place with the different

crews, but are not documented.

3. It has taken steps to discover violations -The employer does daily safety inspections, Daily reports have a section for SAFETY -- where the QC documents items of safety whether for employee misconduct (see Wednesday, July 31, the QC documents items of safety whether for employee misconduct (see Wednesday, July 31, the QC documents items of safety whether for employee misconduct (see Wednesday, July 31, the QC document Continued, FY01 Replacement 2002, Contractor Quality Control/Quality Assurance Report Continued, FY01 Replacement Housing,...) or for safety related problems that need to be addressed, example (Tuesday, Housing,...) or for safety related problems that need to be addressed, example (Tuesday, Housing,...) or wednesday, July 3, 2002). The company has and enforces its employee disciplinary action program, See 3 write ups (2 on 7/31/02 for fall protection and another for an accident that took place in August after this accident.

It has effectively enforced the rules and policies when violations have been discovered.

See the above disciplinary actions taken for previous incidents to this particular accident,

the training records of employees. The employee that caused a safety and/or health infraction was aware the infraction was contrary to the employers safety/health requirements and policies Training records are in this file, safety meetings with documented signatures of who attended are in this file. The employee signed an Employee Safety Orientation acknowledgement form when hired for the FY01 housing project on 24 July 2002. The victim in this case does not appear to have long term or short term memory, so I cannot confirm through him that he is/was aware of the company safety rules, but the company has a signed orientation stating that he does understand the same of the road for safety and same or safety rules. The victim has informed other same of the road for safety and

safety rules, but the company has a signed orientation stating that he does understand the company's safety policy. The victim has informed other employees of the need for safety and fall protection on the job, which was confirmed by employee interviews.

It was speculated that the Miller clip the victim was removing was not nailed to tructural members but into the plywood decking. The Miller clip was running parallel with the outside front of the building. One prepunched hole of 6 (where the nails are driven through) in the clip, appears to be in the structural support under the joint where the ends of the plywood meet. After rechecking the area from underneath, the clip would have been nailed into blocking that runs along the outside perimeter of the building.

The closing conference began on 10 September 2002 at 1459 pm. Employer history is in this file. OSH 200 logs are in this file.

The closing co	onfere	ence began on to september 2002 to the
this file. OSH 200	logs a	re in this life.
Inspection Number		303702237
COVERAGE INFORMATION	¥.	
NATURE AND SCOPE	ole Bo	oxes and Explain Findings:
Check Applica.	Com	plaint Items
		erral Items
×	ACC	ident Investigation Summary & dings
	LEP	
NATURE AND SCOPE		nned pection JAL CIRCUMSTANCES (Mark X and explain all that apply:)
[·	Non	e
		ial of entry (see denial memo)
	Del	ays in conducting the inspection
	Str	rikes
		isdictional ues
	Tra	ide Secrets
	Oth	ner
omments:		

OPENING CONFERENCE NOTES:

On 5 August 2002	at 1106 am; in attendance:
at Laakso	AKOSH Safety Entrees Construction Company
Aike Ritchie	
Jan Revermann	Superintendent, Osborne Construction Company
Jeff Crawford	Superintendent, observe i
Corps of Engine	eers personnel: Safety & Health
John Beier Clyde Wilkerson	Contractor Quality Control
Roger Green	Ouality Assurance
- \ 7h-000	Area Engineer
water Stephenson	Deputy Area Engineer
RECORDKEEPING PRO	GRAMS 1004 requirements)
(Other than 29 CF	R 1904 requirements) have a recordkeeping program relating to any occupational health issues have a recordkeeping program relating to any occupational health issues have a recordkeeping program relating to any occupational health issues
Does the employer	have a recordkeeping program relating to any occupational nearest have a recordkeeping program relating to any occupational nearest lateral have a recordkeeping program relating to any occupational nearest lateral have been program relating to any occupational nearest lateral have been program relating to any occupational nearest lateral have been program relating to any occupational nearest lateral have a record have
	required by OSHA health standards?
Are any programs	Yes No
COMPLIANCE PROGRA	MS rols, PPE, regulated areas, emergency procedures, compliance plans, etc.) rols, PPE, regulated areas, emergency procedures, compliance plans, etc.)
(engineering cont	rols, PPE, regulated areas, emergency procedures, compilance plans, rols, PPE, regulated areas, emergency procedures, compilance plans, and the compilance efforts regarding potential health hazards covered by the continuous continu
scope of the insp	ection.
PERSONAL HYGIENE	FACILITIES AND PRACTICES
a lagrare	change rooms, etc./
Are any required	by OSHA Health Standards
	Yes No
What_	Standards:
HAZARD COMMUNICAT	TON PROGRAM
Written Program (
	x Yes No
MSDS's (all)	
	x Yes No
abeling (adequat	:e <u>) </u>
	x Yes No
Training (complet	ce)
***************************************	x Yes No
Copy MSDS's/Progr	
Copy Habb By 3	
	Yes x No
Comments:	
TIVDOCIII	RE & MEDICAL RECORDS
PACTICALION	ANT) KVACUATION PROCESSIONS
CYSTEMS SAFETY A	ND EMERGENCI RESPONSE
RESPIRATOR PROGRE	AM \ELECTRICAL SAFE WORKPRACTICES
LOCKOUT TAGOUT/	(BubCirican 5.12 West
FIRST AID ELECTRICAL SAFE	WORKPRACTICES
EXPOSITE CONTROL	PLAN
TABORATORY STAND	ARD
ERGONOMIC PROBLE	MS
	Yes No
If yes, co	mplete the items 1 and 2 below. mplete the items 1 and 2 below. mplete the items 1 and 2 below.
	UT ON MOND CIMILATIA CYDODOM ONE - 1
m-+1 #	Of Ambiovees exposed to joe.
b. Total #	of cases for job: or more similarly exposed employees have CTD's; 5% or more CTS cases) or more similarly exposed to job:
a matai #	Ut build 10 Acca cybone and
1 1 4	of cases Int 100:
Other sign	ificant injury/illness trends
	Yes No
If yes, ex	plain.
11 165, 61	•

Inspection Nr. 303702237

EVA	LUATION OF EMPLOYER'S OVERALL SAFETY AND HEALTH PROGRAM
eneral Industry:	Yes No Employer has a Safety & Health Program
	Yes No Written
	Yes No Copy Attached
Construction Indust	Yes No Accident Prevention Frogram
	Yes No Written Yes X No Copy
	Artached
Evaluation of Safet	y and Health Program ladequate 2=Average 3=Above average)
	3 Written S&H
	Program Communication to Employees
 -	3 Enforcement
 -	3 Safety Training
-	Program Health Training Program
<u> </u>	3 Accident Investigation
	Performed
	Taken
Comments:	CLOSING CONFERENCE NOTES:
Pat Laakso Teff Crawford Like Ritchie	D2 at 1459 pm; in attendance: AKOSH Safety Enforcement Officer Superintendent, Osborne Construction Company Project Manager, Osborne Construction Company Paul Herbold, Corporate Safety Officer, Osborne Const Co Paul Herbold, Corporate Such as, but not limited to, abatement ircumstances encountered such as, but not limited to, abatement contest and/or negative employer attitude? If yes, explain below.
1	IVes ly INO
19.Closing Conferen	nce Checklist ("x" as appropriate) No Violations Observed
,	Gave Copy Employer
	Rights
	x Reviewed Hazards & Standards x Discuss Employer
	Rights/Obligations
	x Encouraged Informal Conference
	x Offered Abatement Assistance
	x Discussed Consultation Programs
	Employer/Employee Questionnaires Penresentative
	Closing Conference Held with Employee Representation
	Jointly X Separately
	0 0 -1 / / Date // S.+ 7002
CSHO Signature	Wm. Patrick Cashso Date 16 Sept 2002
Accompanied By	